

# Receiver

## ZR-920P

### General

The ZR-920P Receiver is installed in an ORG-9100A/K Multiple Patient Receiver to receive signals from a transmitter. One receiver receives signals of one channel.

### Safety Information

**CAUTION** A caution alerts the user to possible injury or problems with the instrument associated with its use or misuse such as instrument malfunction, instrument failure, damage to the instrument, or damage to other property.

Pay attention to all safety information in the Operator's Manual or Installation Guide.

#### CAUTION

To avoid the possibility of injury to yourself or damage to the multiple patient receiver:

- Remove the power cord from the multiple patient receiver before installing or removing any component from the multiple patient receiver.
- Use a wrist ground strap or wear rubber gloves to prevent damage from electrostatic discharge.

#### CAUTION

Check that there is no smoke or smell from the multiple patient receiver. If there is smoke or smell, remove the power cord from the multiple patient receiver and contact your Nihon Kohden representative.

This Safety and Performance Information is an extract from the general and safety information sections of the most recent edition of Operator's Manual or Installation Guide. Therefore, the contents of your Operator's Manual or Installation Guide may differ from those of this Safety and Performance Information. For detailed operating procedures, follow the instructions of your Operator's Manual or Installation Guide.

 Manufacturer  
**NIHON KOHDEN CORPORATION**  
1-31-4 Nishiuchiai, Shinjuku-ku,  
Tokyo 161-8560, Japan  
Phone +81 3-5996-8041  
<https://www.nihonkohden.com/>

 European Representative  
**NIHON KOHDEN EUROPE GmbH**  
Raiffeisenstrasse 10, D-61191 Rosbach, Germany  
Phone +49 6003-827-0 Fax +49 6003-827-599